




# 5 steps to successful image processing implementation

**octum** Experts in Machine Vision Solutions.

# 1

## Plan ahead

Incorporate image processing into the system design from the outset.



# 2

## Realistically assess space requirements and installation position


Cameras need a clear view.



# 3

## Train operators


The benefits of a system also depend on its acceptance in everyday life.



# 4

## Clearly define interfaces

Communication with PLC & MES is crucial.



# 5

## Choose flexible systems

in order to be able to respond to product variants or new requirements.





**Do you have any questions?**

**Please contact us.**

**[www.octum.de](http://www.octum.de)**

**+49 7062 91494-0**